Grumpy Joe's UK manufacturer of portable flooring and events furniture

Loughborough Road, East Leake, Leics, LE12 6NZ sales@grumpyjoe.co.uk - 01509 670006 - www.grumpyjoe.co.uk

Parquet Resurfacing Service

Guidelines

When resurfacing parquet flooring, it is required that there is material protruding from the aluminium tray. If there is not excess material above the tray, there is the risk of damaging our machinery when making contact with the aluminium frame.

Please ensure that all of the panels that you bring for reseal have material above the aluminium frame, as shown in the image below.



If the parquet surface is level with or below the aluminium frame, as shown in the image below, it cannot be resurfaced.



Additionally, parquet panels that are missing fingers/blocks must be repaired prior to being resealed. This cost of repair is not included in the price of the resurfacing process and cannot be completed whilst you wait - these panels would need to be left with us. Once repaired, they can be resurfaced. You would then be required to pay for delivery to have these sent back to you or arrange collection or a carrier.

Time taken to sort through flooring may be billable. We recommend that you sort through your flooring using the above guidelines prior to arrival. We reserve the right to reject any floor that does not meet the listed requirements for resealing.